



FUEL PUMP

www.wellxpress.com

 FP-001 Replaces: Ford, Chrysler SS108-19295-1; 4500270	 FP-002 Replaces: GM, Ford E 2065	 FP-003 Replaces: GM GSS340 17100-2
 FP-004 Replaces: Ford, Chrysler, Daewoo 4495820	 FP-005 Replaces: GM, Ford, Chrysler, 4500270	 FP-006 Replaces: GM E3268060
 FP-007 Replaces: Ford, Chrysler, GM 711103QG3	 FP-008 Replaces: GM	 FP-009 Replaces: Citreon 988
 FP-010 Replaces: Ford, Volvo EFP373	 FP-011 Replaces: GM 25162076	 FP-012 Replaces: GM, Ford, Chrysler EEO116-11B1, EFP240



FUEL PUMP

www.wellxpress.com



FP-013

Replaces:

Toyota

**23221-46010,
0580 453 483**



FP-014

Replaces:

Toyota



FP-015

Replaces:

**Mazda,
Mitsubishi**

195130-0082



FP-016

Replaces:

Toyota

23221-15040



FP-017

Replaces:

**GM, Ford,
Toyota**

**XL3U-9350-A,
E2157**



FP-018

Replaces:

**GM, Ford, Toyota
SGUU-9350-B1A**



FP-019

Replaces:

Toyota-Camry

23221-16490



FP-020

Replaces:

**Mazda,
Hyundai, Jeep,
Daewoo**

0963578



FP-021

Replaces:

**GM, Ford
F7SU 9350 CE**



FP-022

Replaces:

GM, Ford

3CSU 9350 AB



FP-023

Replaces:

GM, Ford

XS4U 9350 AA



FP-024

Replaces:


GM, Ford,

FSOU 9350 AA



FUEL PUMP

www.wellxpress.com


 FP-025 Replaces: Toyota	 FP-026 Replaces: Daewoo 5421306	 FP-027 Replaces: GM, Buick
 FP-028 Replaces: Toyota 23221-50060	 FP-029 Replaces: Nissan, Toyota 0 580 454 001	 FP-030 Replaces: Honda E8229
 FP-031 Replaces: Toyota 23220-03020	 FP-032 Replaces: Audi 0 580 254 021	 FP-033 Replaces: VW, Audi, BMW 0 580 453 053
 FP-034 Replaces: VW, Audi, Santana IHO 906 091D	 FP-035 Replaces: Audi SAO 906 091G/A	 FP-036 Replaces: VW, Audi, Ford, IHO 906 091



FUEL PUMP

www.wellxpress.com

	FP-037 Replaces: Audi 895 906 091F 443 201 791D		FP-038 Replaces: BMW		FP-039 Replaces: Opel 0580 453 966, 0580 453 976
	FP-040 Replaces: GM, Buick E3290		FP-041 Replaces: Cherokee 9 580 810 019		FP-042 Replaces: BMW, Audi, Mercedes Benz
	FP-043 Replaces: BMW 0 580 453 021		FP-044 Replaces: Mercedes Benz 000 470 4294		FP-045 Replaces: Mercedes Benz 000 470 60 94
	FP-046 Replaces: Nissan PY3 FK26		FP-047 Replaces: Nissan A42- 7050009 118A		FP-048 Replaces: VW-Jetta, Passat Audi-A6 IGD 919 051B



FUEL PUMP

www.wellxpress.com



FP-049

Replaces:
Toyota,
Mitsubishi,
Honda
23221-43070



FP-050

Replaces:
Toyota
23221-16390



FP-051

Replaces:
Toyota
23221-50040



FP-052

Replaces:
VW, Audi,
Mercedes Benz
0 580 254 950



FP-053

Replaces:
BMW, Peugeot,
Fiat
0 580 254 950



FP-054

Replaces:
Nissan
A42-646010



FP-055

Replaces:
Ford
0 580 464 061



FP-056

Replaces:
Nissan
A42-R22R86



FP-057

Replaces:
Nissan
A42-612R80



FP-058

Replaces:
Audi – 5 Cyls
0 580 254 019



FP-059

Replaces:
VW, Audi,
Mercedes Benz
0 580 254 910





FP-060

Replaces:
VW, Audi,
Mercedes Benz
0 580 254 959



FUEL PUMP

www.wellxpress.com

	FP-061 Replaces: VW, Audi, BMW 0 580 254 957/927		FP-062 Replaces: VW – Jetta, Golf 0 580 254 033		FP-063 Replaces: Volvo 0 580 254 949
	FP-064 Replaces: BMW, Audi, Mercedes Benz 0 580 254 911		FP-065 Replaces: BMW, Audi, Mercedes Benz 0 580 464 070		FP-066 Replaces: Audi 6 cyls 8A0 906 091G
	FP-067 Replaces: BMW, Audi, Mercedes Benz 0 580 453 081		FP-068 Replaces: Ford Buick, GM, Chrysler, Benz 500 270 542B		FP-069 Replaces: Passat 8EO 906 087B
	FP-070 Replaces: Audi – 5 Cyls 443 906 087BE		FP-071 Replaces: Honda, Civic, 0 580 453 452		FP-072 Replaces: Jetta, Audi A6 /C5 8EO 906 087C
	FP-073 Replaces: Jetta 357 906 092C		FP-074 Replaces: VW Jetta, Passat, Ford, 1HO 906 091D		FP-075 Replaces: GM, Ford E3268430, 25168719

Email: wellxpress@wellxpress.com
Asia Contact: 852-2244-5345 / USA Contact: 415-215-2665



FUEL PUMP

www.wellxpress.com



FP-076

Replaces:
GM, Ford
E3044



FP-077

Replaces:
GM, Ford,
Chrysler



FP-078

Replaces:
GM, Ford,
Chrysler




FP-079

Replaces:
GM, Ford,
Chrysler



FP-080

Replaces:
0 580 453 452



FP-081 Replaces:
Toyota Camry 2.2
23220 74021



FP-082

Replaces:
Nissan
17402-51201



FP-083

Replaces:
Mitsubishi
(V31, V33),
Honda



FP-084

Replaces:
Ford



FP-085

Replaces:
ERJ
187197237



FP-086

Replaces:
GM, Ford,
Chrysler
31111-33000



FP-087

Replaces:
Hyundai,
Mazda,
Cherokee



FP-088

Replaces:
Hyundai,
Mazda,
Cherokee
0963578



FP-089

Replaces:
Ford, Mazda,
GM
F8A2-
9H307AC




FP-090 Replaces:
Nissan A42-724

Email: wellxpress@wellxpress.com
Asia Contact: 852-2244-5345 / USA Contact: 415-215-2665




FUEL PUMP

www.wellxpress.com


 FP-091 Replaces: Nissan A42-650016	 FP-092 Replaces: Toyota Camry, Lexus 400, Honda CB7 23221 50010	 FP-093 Replaces: Crown 3.0 23221-46060
 FP-094 Replaces: Audi, BMW, Mercedes Benz, 0 580 463 011	 FP-095 Replaces: Jetta 357 906 092C	 FP-096 Replaces: Cherokee, Mazda 626 0 580 433 434
 FP-097 Replaces: Audi, BMW 9 580 810 020	 FP-098 Replaces: Ford E822	 FP-099 Replaces: Ford 2532 0072
 FP-100 Replaces: Ford G442698219	 FP-101 Replaces: Ford, Chrysler F339-0780	 FP-102 Replaces: Nissan 9 580 810 009
 FP-103 Replaces: Ford 0801 211-E	 FP-104 Replaces: VW Golf, Passat 1HO 919 651 H	 FP-105 Replaces: 330 919 051C

Email: wellxpress@wellxpress.com
Asia Contact: 852-2244-5345 / USA Contact: 415-215-2665



FUEL PUMP

www.wellxpress.com




FP-106

Replaces:

VW Jetta

1GD919 051A




FP-107

Replaces:

**VW Jetta (5 cyl),
Golf, Passat**

1 LO919 051E



FP-108

Replaces:

**DC 001 50 680 /
0 580 305 003**



FP-109

Replaces:

M4UOC10473



FP-110

Replaces:

0975 176 9915



FP-111

Replaces:

330 919 051B




FP-112

Replaces:

VW Passat B5


3BO 919 051C



FP-113


Replaces:

**VW Golf, Passat
B4, Jetta (5 cyl)**




FUEL PUMP

www.wellxpress.com




FP-114

Replaces:
A6, C5



FP-115

Replaces:
Mitsubishi



FP-116

Replaces:
VW Jetta



FP-117 Replaces:
VW E22 041 058 / 8DO 906 089